

Flood Control Project Maintenance Levee Inspections

Levee Log Report By Levee Mile - Updated 8/23/2021

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | Bank | Unit Miles | Inspector |
|------------------------------|-------|------------|--------------|
| Unit No. 01 Sacramento River | Right | 3.47 | David Julian |

| Entry No | Levee Mile | | Category | Item | Location | Comment | Source |
|----------|------------|-----|----------|------|----------|---------|---------|
| | Start | End | | | | | Permits |

| | | | | | | | |
|---|------|------|------|-------|-------|---|--------------|
| 8 | 0.00 | 0.00 | Gate | Metal | Crown | Pipe gate across levee with metal fencing on landside and waterside slopes. Entry Last Updated : 1/27/2021 | H_LL_GENERAL |
|---|------|------|------|-------|-------|---|--------------|

| | | | | | | | |
|----|------|------|------|------|----------|--|----------------------|
| 47 | 0.00 | 0.00 | UCIP | Pipe | Crossing | DS_ID:259 EP_NO: 17681 Crossing Status: Indicator Found FIELD_STRUCT_DESC: 1 of 2: 60-inch steel sewer force main tunneled under the Sacramento River and its levees, approximately 76 feet below the crown. Ramp on the landside (LS) slope. (Plans to place two 60-inch parallel force main sewer pipes by tunneling under the Sacramento River and its levees, construct a temporary access ramp, remove an existing ramp and bridge, and construct a maintenance ramp on the LS slope of the levee authorized under Permit No. 17681, 2004 - Sacramento Regional County Sanitation District). Entry Last Updated : 4/17/2021 | UCIPAPR2021 17681 |
|----|------|------|------|------|----------|--|----------------------|

| | | | | | | | |
|----|------|------|------|-------|------------|--|----------|
| 82 | 0.00 | 0.00 | Gate | Metal | Water Side | Pipe gate is at WS toe road. Entry Last Updated : 1/27/2021 | LEVEELOG |
|----|------|------|------|-------|------------|--|----------|

| | | | | | | | |
|-----|------|------|------|------|--|--|-------------|
| 114 | 0.00 | 0.00 | UCIP | Pipe | | DS_ID:25103 EP_NO: Crossing Status: Not Found FIELD_STRUCT_DESC: *REMOVED* 30-inch iron water line, at an unknown depth. [Additional Reference(s): Drawing 50-04-2275 dated March 1946, Sacramento River, California Flood Control Levee Construction West Levee Sacramento River at Bryte's Bend indicates line was scheduled to be removed. The drawing is associated with USACE Sacramento O&M Manual, Unit 116, Aug 1955, Revised 29 Dec 2016; Drawing No. 50-04-2275, Sheet 1 and 2, shown as 30-inch iron pipe, (STA 33+80), was scheduled to be removed] Entry Last Updated : 4/17/2021 | UCIPAPR2021 |
|-----|------|------|------|------|--|--|-------------|

| | | | | | | | |
|-----|------|------|-------|------------|------------|---|------------------|
| 318 | 0.00 | 0.41 | Fence | Chain Link | Water Side | Metal fence with barbed wire along levee toe road delineates Sac Maintenance Yard property. Entry Last Updated : 3/26/2015 | LEVEELOG 3380 |
|-----|------|------|-------|------------|------------|---|------------------|

| | | | | | | | |
|-----|------|------|-----------|--------|------------|---|----------|
| 338 | 0.00 | 0.60 | Revetment | Rubble | Water Side | Concrete rubble on water side, at small area of sloughing of levee. Continues downstream. Entry Last Updated : 3/26/2015 | LEVEELOG |
|-----|------|------|-----------|--------|------------|---|----------|

| | | | | | | | |
|-----|------|------|-----------|--------------|-------|---|----------|
| 341 | 0.00 | 0.62 | Structure | Pole - Light | Crown | Light fixtures spaced approximately 40 feet apart along crown of levee. Entry Last Updated : 1/27/2021 | LEVEELOG |
|-----|------|------|-----------|--------------|-------|---|----------|

Flood Control Project Maintenance Levee Inspections

Levee Log Report By Levee Mile - Updated 8/23/2021

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | Bank | Unit Miles | Inspector |
|------------------------------|-------|------------|--------------|
| Unit No. 01 Sacramento River | Right | 3.47 | David Julian |

| Entry No | Levee Mile | | Category | Item | Location | Comment | Source |
|----------|------------|-----|----------|------|----------|---------|---------|
| | Start | End | | | | | Permits |

| | | | | | | | |
|----|------|------|------|------|----------|--|----------------------|
| 49 | 0.00 | 0.00 | UCIP | Pipe | Crossing | DS_ID:481 EP_NO: 17681 Crossing Status: Indicator Found FIELD_STRUCT_DESC: 2 of 2: 60-inch steel sewer force main tunneled under the Sacramento River and its levees, approximately 76 feet below the crown. Ramp on the landside (LS) slope. (Plans to place two 60-inch parallel force main sewer pipes by tunneling under the Sacramento River and its levees, construct a temporary access ramp, remove an existing ramp and bridge, and construct a maintenance ramp on the LS slope of the levee authorized under Permit No. 17681, 2004 - Sacramento Regional County Sanitation District). Entry Last Updated : 4/17/2021 | UCIPAPR2021 17681 |
|----|------|------|------|------|----------|--|----------------------|

| | | | | | | | |
|-----|------|------|------|--------|-------|--|----------|
| 301 | 0.00 | 0.00 | Mark | Marker | Crown | LM 0.0 marker. Entry Last Updated : 3/12/2015 | LEVEELOG |
|-----|------|------|------|--------|-------|--|----------|

| | | | | | | | |
|----|------|------|-----------|----------------|-----------|--|--------------|
| 10 | 0.02 | 0.02 | Structure | Pole - Utility | Land Side | Powerline pole with anchor on the landward slope of the levee. Entry Last Updated : 1/27/2021 | H_LL_GENERAL |
|----|------|------|-----------|----------------|-----------|--|--------------|

| | | | | | | | |
|-----|------|------|-----------|----------------|-----------|---|----------|
| 303 | 0.07 | 0.07 | Structure | Pole - Utility | Land Side | Powerline pole near LS toe. Entry Last Updated : 1/27/2021 | LEVEELOG |
|-----|------|------|-----------|----------------|-----------|---|----------|

| | | | | | | | |
|-----|------|------|-------|-------|-----------|---|----------|
| 302 | 0.07 | 0.16 | Fence | Metal | Land Side | Metal fence near LS toe adjacent to Riverbank Rd. Entry Last Updated : 3/12/2015 | LEVEELOG |
|-----|------|------|-------|-------|-----------|---|----------|

| | | | | | | | |
|---|------|------|------|------|----------|---|-------------|
| 6 | 0.10 | 0.10 | UCIP | Pipe | Crossing | DS_ID:272 EP_NO: Crossing Status: Not Found FIELD_STRUCT_DESC: 24-inch steel irrigation pipe through the levee, 18 feet below the crown. Pump and gate valve on the waterside (WS). Surge chamber on the landside (LS). [Additional Reference(s): USACE Sacramento O&M Manual, Unit 116, August 1955, Revised 29 Dec 2016, (RM 62.5), also referenced as Sta 31+80 under As-Built Drawing 50-04-2273, Sheet 1, listed as 24-inch steel pipe installed and three pipes removed 24-inch concrete pipe, 18-inch iron pipe and 10-inch pipe; work at Sta 31+80 also referenced in Drawing No. 50-4-2275 Sheet 1 and 2] Entry Last Updated : 4/17/2021 | UCIPAPR2021 |
|---|------|------|------|------|----------|---|-------------|

| | | | | | | | |
|-----|------|------|-----------|----------------|-----------|---|----------|
| 304 | 0.11 | 0.11 | Structure | Pole - Utility | Land Side | Powerline pole with anchor at LS toe. Entry Last Updated : 1/27/2021 | LEVEELOG |
|-----|------|------|-----------|----------------|-----------|---|----------|

| | | | | | | | |
|-----|------|------|-------|-------|-----------|--|----------|
| 305 | 0.13 | 0.13 | Fence | Metal | Land Side | Metal fence goes from toe 1/2 way up LS slope. Entry Last Updated : 3/26/2015 | LEVEELOG |
|-----|------|------|-------|-------|-----------|--|----------|

Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|------------|------------|---|----------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 306 | 0.13 | 0.13 | Structure | Sign | Land Side | Stop sign at LS toe. Entry Last Updated : 3/12/2015 | LEVEELOG | | |
| 308 | 0.14 | 0.14 | Ramp | Ramp | Land Side | Paved ramp to Bryte Yard entry. Entry Last Updated : 3/12/2015 | LEVEELOG | | |
| 311 | 0.16 | 0.16 | Fence | Metal | Land Side | Metal fence from Bryte Yard gate to LS slope. Entry Last Updated : 3/12/2015 | LEVEELOG | | |
| 310 | 0.16 | 0.16 | Gate | Metal | Land Side | Metal pipe gate at top of paved ramp at entry to Bryte Yard. Entry Last Updated : 3/12/2015 | LEVEELOG | | |
| 309 | 0.16 | 0.16 | Structure | Sign | Land Side | Bryte Yard sign by LS toe. Entry Last Updated : 3/12/2015 | LEVEELOG | | |
| 312 | 0.16 | 0.24 | Fence | Metal | Land Side | Metal fence on LS slope connecting to fence from Bryte Yard gate. Entry Last Updated : 3/26/2015 | LEVEELOG | | |
| 314 | 0.20 | 0.20 | Wall | Retaining | Land Side | Metal retaining wall contains dirt pad on LS. Entry Last Updated : 3/12/2015 | LEVEELOG | | |
| 313 | 0.20 | 0.20 | Gate | Metal | Land Side | Metal gate on LS hinge leading to dirt pad. Entry Last Updated : 3/12/2015 | LEVEELOG | | |
| 315 | 0.20 | 0.20 | Ramp | Ramp | Water Side | Small dirt ramp to WS toe road. Entry Last Updated : 3/12/2015 | LEVEELOG | | |
| 316 | 0.24 | 0.24 | Fence | Chain Link | Crossing | Chain link fence with barbed wire across the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 1 | 0.25 | 0.41 | Fence | Chain Link | Crown | Chain link fence with barbed wire on levee crown along Bryte Yard grounds. Entry Last Updated : 4/8/2015 | LEVEELOG | | |

Flood Control Project Maintenance Levee Inspections

Levee Log Report By Levee Mile - Updated 8/23/2021

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | Bank | Unit Miles | Inspector |
|------------------------------|-------|------------|--------------|
| Unit No. 01 Sacramento River | Right | 3.47 | David Julian |

| Entry No | Levee Mile | | Category | Item | Location | Comment | Source |
|----------|------------|-----|----------|------|----------|---------|---------|
| | Start | End | | | | | Permits |

| | | | | | | | |
|-----|------|------|------|------|--|--|-------------|
| 113 | 0.25 | 0.25 | UCIP | Pipe | | DS_ID:25546 EP_NO: Crossing Status: Found FIELD_STRUCT_DESC: 12-inch corrugated metal drainage pipe through the levee, 19.0 feet below levee crown. [Additional Reference(s): Drawing No. 50-04-4179, Sheet 11.2 and 18.1, pdf page 9 and 17 of 19, associated with USACE Sacramento O&M Manual, Unit 116, August 1955, Revised 29 Dec 2016, shows 12-inch CMP referenced as Sta 44+92 (Site Mile 62.25 RT)]. Entry Last Updated : 4/17/2021 | UCIPAPR2021 |
|-----|------|------|------|------|--|--|-------------|

| | | | | | | | |
|-----|------|------|------|------|--|--|-------------|
| 115 | 0.32 | 0.32 | UCIP | Pipe | | DS_ID:25545 EP_NO: Crossing Status: Found FIELD_STRUCT_DESC: 12-inch corrugated metal drainage pipe through the levee, 23.3 feet below levee crown. [Additional Reference(s): Drawing No. 50-04-4179, Sheet 11.2 and 18.1, pdf page 9 and 17 of 19, associated with USACE Sacramento O&M Manual, Unit 116, August 1955, Revised 29 Dec 2016, shows 12-inch CMP referenced as Sta 48+62 (Site Mile 62.25 RT)]. Entry Last Updated : 4/17/2021 | UCIPAPR2021 |
|-----|------|------|------|------|--|--|-------------|

| | | | | | | | |
|----|------|------|-----------|----------|-----------|---|-----------------------|
| 46 | 0.33 | 0.33 | Structure | Building | Land Side | Restaurant on the landside slope. Entry Last Updated : 1/27/2021 | USGSQUAD_EGIS 6036 |
|----|------|------|-----------|----------|-----------|---|-----------------------|

| | | | | | | | |
|---|------|------|------|------------|-------|--|----------|
| 5 | 0.37 | 0.37 | Gate | Chain Link | Crown | Chain link gate with barbed wire at top of paved ramp from Bryte Yard. Entry Last Updated : 1/27/2021 | LEVEELOG |
|---|------|------|------|------------|-------|--|----------|

| | | | | | | | |
|---|------|------|------|------|------------|---|----------|
| 3 | 0.37 | 0.37 | Ramp | Ramp | Water Side | Bottom of paved ramp from Bryte Yard to WS path below levee crown. Ramp has metal railing. Entry Last Updated : 4/8/2015 | LEVEELOG |
|---|------|------|------|------|------------|---|----------|

| | | | | | | | |
|-----|------|------|------|------|--|---|-------------|
| 103 | 0.38 | 0.38 | UCIP | Pipe | | DS_ID:25547 EP_NO: Crossing Status: Found FIELD_STRUCT_DESC: 6-inch high-density polyethylene (HDPE) drainage pipe through the levee, unknown depth below levee crown. First drainage pit with grid is located in the middle of paved road, second is between 2 trailers toward levee toe inline with the first one. Entry Last Updated : 4/17/2021 | UCIPAPR2021 |
|-----|------|------|------|------|--|---|-------------|

| | | | | | | | |
|-----|------|------|-----------|------|------------|---|----------|
| 319 | 0.41 | 0.60 | Revetment | Rock | Water Side | Rock riprap on river bank below toe road. Entry Last Updated : 3/12/2015 | LEVEELOG |
|-----|------|------|-----------|------|------------|---|----------|

| | | | | | | | |
|-----|------|------|------|-------|------------|--|----------|
| 317 | 0.41 | 0.41 | Gate | Metal | Water Side | Inoperable metal gate with barbed wire prohibits upstream access along levee road. Entry Last Updated : 1/27/2021 | LEVEELOG |
|-----|------|------|------|-------|------------|--|----------|

Flood Control Project Maintenance Levee Inspections

Levee Log Report By Levee Mile - Updated 8/23/2021

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|--|--|--|--|--|-------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | Right | 3.47 | David Julian |

| Entry No | Levee Mile | | Category | Item | Location | Comment | Source |
|----------|------------|------|-----------|-------------|------------|--|-----------------------|
| | Start | End | | | | | Permits |
| 107 | 0.41 | 0.41 | UCIP | Pipe | | DS_ID:25549 EP_NO: 2912 Crossing Status: Not Found FIELD_STRUCT_DESC: 6-inch corrugated metal drainage pipe through the levee, 15.5 feet below levee crown. (6-inch galvanized iron pipe authorized under Permit 2912, 1958 - Department of Water Resources). [Additional Reference(s): DWR Levee Log, 2005 (HLM 0.41 at a depth of 6.4 feet below the crown). Drawing No. 50-04-4179, Sheet 11.2 and 18.1, pdf page 9 and 17 of 19, associated with USACE Sacramento O&M Manual, Unit 116, August 1955, Revised 29 Dec 2016, shows combination of 6-inch and 8-inch CMP referenced as Sta 53+33] Entry Last Updated : 4/17/2021 | UCIPAPR2021 2912 |
| 320 | 0.42 | 0.42 | Structure | Sign | Water Side | No Trespassing sign on the waterside. Entry Last Updated : 1/27/2021 | LEVEELOG |
| 110 | 0.43 | 0.43 | UCIP | Pipe | | DS_ID:25544 EP_NO: Crossing Status: Found FIELD_STRUCT_DESC: 8-inch steel drainage pipe through the levee, 12.1 feet below levee crown. [Additional Reference(s): Drawing No. 50-04-4179, Sheet 11.2 and 18.1, pdf page 9 and 17 of 19, associated with USACE Sacramento O&M Manual, Unit 116, August 1955, Revised 29 Dec 2016, shows 8-inch CMP referenced as Sta 54+53 (Site Mile 62.25 RT)]. Entry Last Updated : 4/17/2021 | UCIPAPR2021 |
| 249 | 0.44 | 0.74 | Structure | Building | Crown | Building for test laboratory for hydraulic model studies. Entry Last Updated : 1/27/2021 | USGSQUAD_EGIS 2950 |
| 321 | 0.44 | 0.44 | Structure | Tower | Water Side | 3 wood mooring towers by shore. Entry Last Updated : 3/12/2015 | LEVEELOG |
| 327 | 0.45 | 0.45 | Structure | Gauge | Crown | CIMIS station on crown of levee. Entry Last Updated : 3/26/2015 | LEVEELOG |
| 328 | 0.46 | 0.46 | Structure | Control Box | Crown | Utility box with wire leading to small tower. Entry Last Updated : 3/12/2015 | LEVEELOG |

Flood Control Project Maintenance Levee Inspections

Levee Log Report By Levee Mile - Updated 8/23/2021

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|--|--|--|--|--|-------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | Right | 3.47 | David Julian |

| Entry No | Levee Mile | | Category | Item | Location | Comment | Source |
|----------|------------|-----|----------|------|----------|---------|---------|
| | Start | End | | | | | Permits |

| | | | | | | | |
|-----|------|------|------|------|--|---|-------------|
| 108 | 0.46 | 0.46 | UCIP | Pipe | | DS_ID:25552 EP_NO: Crossing Status: Not Found FIELD_STRUCT_DESC: 9-inch steel drainage pipe through the levee, 17 feet below levee crown. [Additional Reference(s): Drawing No. 50-04-4179, Sheet 11.2 and 18.1, pdf page 9 and 17 of 19, associated with USACE Sacramento O&M Manual, Unit 116, August 1955, Revised 29 Dec 2016, shows 9-inch steel pipe referenced as Sta 56+02 (Site Mile 62.25 RT)] Entry Last Updated : 4/17/2021 | UCIPAPR2021 |
|-----|------|------|------|------|--|---|-------------|

| | | | | | | | |
|-----|------|------|------|--------|------------|---|----------|
| 322 | 0.47 | 0.47 | Mark | Marker | Water Side | 0.5 marker by WS hinge. Entry Last Updated : 3/12/2015 | LEEVELOG |
|-----|------|------|------|--------|------------|---|----------|

| | | | | | | | |
|-----|------|------|-----------|----------|-------|--|----------|
| 331 | 0.47 | 0.47 | Structure | Building | Crown | Appears to be a small portable storage shed on crown of levee. Entry Last Updated : 3/12/2015 | LEEVELOG |
|-----|------|------|-----------|----------|-------|--|----------|

| | | | | | | | |
|-----|------|------|---------------|-------------|------------|--|----------|
| 323 | 0.48 | 0.60 | Miscellaneous | Landscaping | Water Side | Landscaping starts on WS slope above toe road. Entry Last Updated : 3/12/2015 | LEEVELOG |
|-----|------|------|---------------|-------------|------------|--|----------|

| | | | | | | | |
|-----|------|------|------|------|--|---|-------------|
| 104 | 0.48 | 0.48 | UCIP | Pipe | | DS_ID:25550 EP_NO: Crossing Status: Not Found FIELD_STRUCT_DESC: 6-inch vitrified clay drainage pipe through the levee, 16.1 feet below levee crown. [Additional Reference(s): Drawing No. 50-04-4179, Sheet 11.2 and 18.1, pdf page 9 and 17 of 19, associated with USACE Sacramento O&M Manual, Unit 116, August 1955, Revised 29 Dec 2016, shows combination of 6-inch vitrified clay pipe and 8-inch CMP referenced as Sta 56+96 (Site Mile 62.25 RT)] Entry Last Updated : 4/17/2021 | UCIPAPR2021 |
|-----|------|------|------|------|--|---|-------------|

| | | | | | | | |
|----|------|------|--------|--------------|------------|---|-------------|
| 58 | 0.49 | 0.56 | Aerial | High Voltage | Water Side | Overhead powerline above waterside hinge. Entry Last Updated : 1/27/2021 | GEILEVEELOG |
|----|------|------|--------|--------------|------------|---|-------------|

| | | | | | | | |
|-----|------|------|-----------|-------|-------|---|----------|
| 332 | 0.50 | 0.50 | Structure | Other | Crown | Large generator on levee crown. Entry Last Updated : 1/27/2021 | LEEVELOG |
|-----|------|------|-----------|-------|-------|---|----------|

| | | | | | | | |
|-----|------|------|-----------|-------------|-------|--|----------|
| 333 | 0.50 | 0.50 | Structure | Control Box | Crown | Utility box located on crown of levee. Entry Last Updated : 3/12/2015 | LEEVELOG |
|-----|------|------|-----------|-------------|-------|--|----------|

| | | | | | | | |
|-----|------|------|-----------|------|-------|---|----------|
| 325 | 0.53 | 0.53 | Structure | Sign | Crown | Sign on levee crest on Sac Maintenance Yard property. Entry Last Updated : 3/12/2015 | LEEVELOG |
|-----|------|------|-----------|------|-------|---|----------|

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|---------------|------------|---|-----------------------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 68 | 0.53 | 0.53 | Structure | Gauge | Water Side | Stream gaging station on the waterward side. Entry Last Updated : 3/25/2015 | H_LL_GENERAL 12864 | | |
| 73 | 0.56 | 0.56 | Structure | Manhole Cover | Crown | Sewer line access plate on the crown. Entry Last Updated : 1/27/2021 | USACEPI | | |
| 111 | 0.58 | 0.58 | UCIP | Pipe | | DS_ID:25582 EP_NO: Crossing Status: Not Found FIELD_STRUCT_DESC: 3/4-inch gas line of unknown material crossing landside levee slope enters a Sac Yard building on levee crown. Discovered during revision of Sacramento Maintenance Yard Site Rehabilitation - Phase I Pavement and Utilities as-built drawings (Sheet 009 Existing Utility System, Drawing No. C1-05). Entry Last Updated : 4/17/2021 | UCIPAPR2021 | | |
| 106 | 0.58 | 0.58 | UCIP | Pipe | | DS_ID:25583 EP_NO: Crossing Status: Found FIELD_STRUCT_DESC: 6-inch VCP storm drainage pipe, gridded concrete drainage box in drainage ditch at LS toe. Discovered during revision of Sacramento Maintenance Yard Site Rehabilitation - Phase I Pavement and Utilities as-built drawings (Sheet 009 Existing Utility System, Drawing No. C1-05). Entry Last Updated : 4/17/2021 | UCIPAPR2021 | | |
| 335 | 0.58 | 0.58 | Structure | Sign | Water Side | Small sign located on water side hinge near the crown. Entry Last Updated : 3/12/2015 | LEVEELOG | | |
| 336 | 0.59 | 0.59 | Structure | Building | Crown | Small storage shed located on crown of levee. Entry Last Updated : 3/12/2015 | LEVEELOG | | |
| 109 | 0.62 | 0.62 | UCIP | Pipe | | DS_ID:25584 EP_NO: Crossing Status: Found FIELD_STRUCT_DESC: 12-inch CMP storm drainage pipe. 36-inch CMP manhole on levee crown and storm drain pipe outlet in drainage ditch at LS toe. Discovered during revision of Sacramento Maintenance Yard Site Rehabilitation - Phase I Pavement and Utilities as-built drawings (Sheet 010 Existing Utility System, Drawing No. C1-06). Entry Last Updated : 4/17/2021 | UCIPAPR2021 | | |
| 342 | 0.62 | 0.62 | Structure | Tank | Crown | Small propane tank located on crown of levee. Entry Last Updated : 3/12/2015 | LEVEELOG | | |

Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|----------------|-----------|---|-------------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 344 | 0.63 | 0.63 | Structure | Building | Crown | Vehicle washing station on levee crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 345 | 0.64 | 0.64 | Structure | Building | Crown | Portable storage shed located on crown of levee. Entry Last Updated : 3/12/2015 | LEVEELOG | | |
| 84 | 0.69 | 1.06 | At Grade | Road / Highway | Land Side | Riverbank Street along landward toe of levee. Entry Last Updated : 3/17/2015 | GEILEVEELOG | | |
| 363 | 0.70 | 0.75 | Fence | Chain Link | Land Side | Fence is on toe of the landside of the levee. Runs up the side of the levee to the crown, then runs along the crown. Fence ends at edge of property of the Sacramento maintenance yard. Entry Last Updated : 3/12/2015 | LEVEELOG | | |
| 364 | 0.72 | 0.72 | Structure | Sign | Land Side | Sign located on landside toe of levee, near Riverbank Road. Sign says "Bump 15 mph". Entry Last Updated : 3/12/2015 | LEVEELOG | | |
| 362 | 0.72 | 0.72 | Ramp | Ramp | Land Side | Ramp from Riverbank Road to levee is paved. Entry Last Updated : 3/12/2015 | LEVEELOG | | |
| 361 | 0.73 | 0.73 | Gate | Metal | Land Side | Metal gate on landside of levee limits access from Riverbank Road. Entry Last Updated : 3/12/2015 | LEVEELOG | | |
| 365 | 0.73 | 0.73 | Structure | Sign | Land Side | Small white sign, unmarked, on the landside. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 88 | 0.74 | 1.06 | Aerial | Communications | Land Side | Overhead telephone line along the landside toe. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 366 | 0.74 | 0.74 | Structure | Pole - Utility | Land Side | Power pole located on landside toe of levee next to Riverbank Road. Guy wires are anchored to the toe of the levee. Entry Last Updated : 3/26/2015 | LEVEELOG | | |
| 371 | 0.75 | 0.75 | Structure | Sign | Land Side | Stop sign located on landside at the intersection of Riverbank Road and Todhunter Avenue. Entry Last Updated : 3/26/2015 | LEVEELOG | | |
| 367 | 0.75 | 0.75 | Structure | Sign | Land Side | Sign located on landside toe of levee next to the intersection of Riverbank Road and Todhunter Avenue. Entry Last Updated : 3/12/2015 | LEVEELOG | | |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|---------------|-----------------|------------|--|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | |
| | Start | End | | | | | Permits | |
| 370 | 0.75 | 0.75 | Structure | Monitoring Well | Crown | Two monitoring wells located on crest of levee. Entry Last Updated : 3/12/2015 | LEEVELOG | |
| 369 | 0.75 | 0.75 | Structure | Other | Crown | Solar panel located on crown of levee. Entry Last Updated : 1/27/2021 | LEEVELOG | |
| 372 | 0.75 | 0.75 | Ramp | Ramp | Water Side | Ramp leads from levee crown towards the river. This ramp has a concrete gutter. Entry Last Updated : 3/26/2015 | LEEVELOG | |
| 368 | 0.75 | 0.75 | Structure | Stairs | Land Side | Concrete stairs located on landside of levee near footpath, leading to Riverbank Road. Entry Last Updated : 3/12/2015 | LEEVELOG | |
| 374 | 0.76 | 0.76 | Structure | Sign | Water Side | Flood history display, located on water side hinge. Restoration sign also present. Entry Last Updated : 3/12/2015 | LEEVELOG | |
| 373 | 0.76 | 1.06 | At Grade | Road / Highway | Crown | Levee crown is paved. Entry Last Updated : 3/12/2015 | LEEVELOG | |
| 375 | 0.76 | 0.76 | Structure | Sign | Water Side | Sign located on water side hinge. Entry Last Updated : 3/12/2015 | LEEVELOG | |
| 377 | 0.76 | 1.30 | Miscellaneous | Mitigation Site | Water Side | Walking/bicycle path runs through the restoration site on the water side of the levee. Entry Last Updated : 3/12/2015 | LEEVELOG | |
| 376 | 0.76 | 1.14 | Fence | Post & Cable | Land Side | Cable fence located on landside toe next to Riverbank Road. Entry Last Updated : 3/12/2015 | LEEVELOG | |
| 378 | 0.77 | 0.77 | Ramp | Ramp | Land Side | Paved ramp leading from levee crown to Riverbank Road. Has a concrete gutter. Entry Last Updated : 3/12/2015 | LEEVELOG | |
| 379 | 0.77 | 0.77 | Structure | Sign | Land Side | Sign located on landside of levee. Entry Last Updated : 3/12/2015 | LEEVELOG | |
| 380 | 0.77 | 0.77 | Structure | Sign | Land Side | Sign located on land side. Entry Last Updated : 3/12/2015 | LEEVELOG | |
| 381 | 0.78 | 0.78 | Structure | Sign | Land Side | Sign on land side adjacent to ramp- "Bike Route End". Entry Last Updated : 3/26/2015 | LEEVELOG | |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|-----------------|-----------|---|----------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 382 | 0.78 | 0.78 | Structure | Monitoring Well | Crown | Monitoring well located on crest of levee, cover is painted white. Entry Last Updated : 3/12/2015 | LEVEELOG | | |
| 384 | 0.79 | 0.86 | Ramp | Ramp | Land Side | Handicap accessible concrete ramp with railings on both sides leading to the levee crown from Riverbank Road. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 385 | 0.79 | 0.79 | Structure | Sign | Land Side | Sign located on landside hinge. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 383 | 0.80 | 0.80 | Structure | Sign | Land Side | Stop sign at the end of the ramp next to Riverbank Road. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 386 | 0.80 | 0.80 | Structure | Sign | Land Side | Sign located on landside near Riverbank Road. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 387 | 0.80 | 0.80 | Structure | Sign | Land Side | Sign located on landside next to Riverbank Road. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 388 | 0.86 | 0.86 | Structure | Sign | Land Side | Sign located on landside next to Riverbank Road. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 389 | 0.86 | 0.86 | Structure | Sign | Land Side | Handicap parking sign located on landside next to Riverbank Road. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 390 | 0.86 | 0.86 | Structure | Pad | Land Side | Concrete pad on landside next to Riverbank Road, used as a handicap parking spot. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 7 | 0.90 | 0.90 | Structure | Sign | Crown | Sign located on crown of levee. Entry Last Updated : 8/20/2020 | LEVEELOG | | |
| 392 | 0.94 | 0.94 | Structure | Monitoring Well | Crown | Monitoring well located on crown of levee. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 393 | 0.96 | 0.96 | Structure | Sign | Land Side | Sign located on landside next to power pole, near Riverbank Road. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 394 | 1.04 | 1.04 | Structure | Sign | Crown | Sign indicates that the pavement ends along the levee crown, and also indicates that the bike route ends. Entry Last Updated : 3/26/2015 | LEVEELOG | | |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|-----------------|------------|---|----------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 396 | 1.06 | 1.06 | Structure | Monitoring Well | Crown | Monitoring well located on crown of levee. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 395 | 1.06 | 1.06 | Structure | Sign | Crown | Sign located on crown of levee. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 397 | 1.06 | 1.06 | Structure | Sign | Land Side | Sign located next to power pole near the end of Riverbank Road. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 398 | 1.07 | 1.07 | Gate | Metal | Land Side | Gate restricts access to levee from the end of Riverbank Road. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 399 | 1.14 | 1.30 | Fence | Wrought Iron | Land Side | Fence located on landside next to road. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 400 | 1.15 | 1.15 | Structure | Control Box | Water Side | Five recycled water control boxes on the waterside slope. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 401 | 1.25 | 1.25 | Structure | Monitoring Well | Crown | Monitoring well located on crown of levee. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 402 | 1.25 | 1.25 | Structure | Monitoring Well | Crown | Monitoring well located on crown of levee. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 403 | 1.30 | 1.30 | Gate | Metal | Crown | Metal gate on crown of levee. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 405 | 1.31 | 1.32 | Fence | Wood | Land Side | Wood fence along landside toe. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 404 | 1.31 | 1.32 | At Grade | Road / Highway | Crown | Levee crown is paved. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 474 | 1.31 | 2.01 | At Grade | Bikepath | Water Side | Gravel pedesrian/bikepath by river. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 83 | 1.32 | 1.99 | At Grade | Road / Highway | Water Side | Concrete sidewalk on water side of crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|---------------|----------------|------------|--|-------------------|--------------|
| Unit No. 01 Sacramento River | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | |
| | Start | End | | | | | Permits | |
| 407 | 1.32 | 1.99 | At Grade | Road / Highway | Crown | Levee crown is now a paved residential street. Name of road is River Crest Drive. Sidewalk and gutter have drop inlets every so often. Entry Last Updated : 1/27/2021 | LEVEELOG | |
| 406 | 1.32 | 1.32 | Structure | Control Box | Crown | Four power control boxes located on crown of levee. Entry Last Updated : 3/17/2015 | LEVEELOG | |
| 408 | 1.33 | 1.33 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | |
| 409 | 1.33 | 1.33 | Structure | Sign | Crown | Right arrow sign on levee crown. Entry Last Updated : 3/17/2015 | LEVEELOG | |
| 411 | 1.33 | 1.33 | Ramp | Ramp | Land Side | Westlake Drive leads down from the levee crown to the landside. Entry Last Updated : 1/27/2021 | LEVEELOG | |
| 412 | 1.33 | 1.33 | Structure | Control Box | Crown | Monument control box on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | |
| 2 | 1.34 | 1.35 | Structure | Building | Water Side | Partially constructed home on the waterside shoulder. Entry Last Updated : 1/27/2021 | LEVEELOG 17967 | |
| 86 | 1.34 | 1.97 | Miscellaneous | Irrigation | Land Side | Irrigation on the landside slope. Entry Last Updated : 1/27/2021 | LEVEELOG 15793 | |
| 414 | 1.34 | 1.97 | Miscellaneous | Landscaping | Land Side | Landscaping on the landside slope. Entry Last Updated : 1/27/2021 | LEVEELOG 15793 | |
| 413 | 1.34 | 1.34 | Structure | Sign | Land Side | Street sign at the intersection of River Crest and Westlake. Entry Last Updated : 3/17/2015 | LEVEELOG | |
| 99 | 1.35 | 1.35 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | |
| 87 | 1.35 | 1.36 | Structure | Building | Water Side | House on the waterside shoulder. Entry Last Updated : 1/27/2021 | LEVEELOG 17559 | |
| 89 | 1.37 | 1.38 | Structure | Building | Water Side | House on the waterside shoulder. Entry Last Updated : 1/27/2021 | LEVEELOG 17590 | |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|--------------|------------|---|-------------------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 417 | 1.37 | 1.37 | Structure | Control Box | Water Side | PG&E control box located next to sidewalk on the waterside hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 90 | 1.38 | 1.39 | Structure | Building | Water Side | House on the waterside shoulder. Entry Last Updated : 1/27/2021 | LEVEELOG 17661 | | |
| 91 | 1.39 | 1.41 | Structure | Building | Water Side | House on the waterside shoulder. Entry Last Updated : 1/27/2021 | LEVEELOG 17660 | | |
| 100 | 1.39 | 1.39 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 419 | 1.40 | 1.40 | Structure | Other | Crown | Metal bench on concrete pad on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 422 | 1.42 | 1.43 | Structure | Building | Water Side | House on the waterside shoulder. Entry Last Updated : 1/27/2021 | LEVEELOG 17699 | | |
| 423 | 1.42 | 1.98 | At Grade | Bikepath | Land Side | Concrete pedestrian/bike path on the landside toe, next to road. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 421 | 1.42 | 1.42 | Structure | Mailbox | Crown | Community mailbox on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 92 | 1.43 | 1.45 | Structure | Building | Water Side | House on the waterside shoulder. Entry Last Updated : 1/27/2021 | LEVEELOG 17943 | | |
| 93 | 1.45 | 1.46 | Structure | Building | Water Side | House on the waterside shoulder. Entry Last Updated : 1/27/2021 | LEVEELOG 17948 | | |
| 424 | 1.45 | 1.45 | Structure | Control Box | Crown | PG&E control box on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 94 | 1.46 | 1.47 | Structure | Building | Water Side | House on the waterside shoulder. Entry Last Updated : 1/27/2021 | LEVEELOG 17944 | | |
| 426 | 1.46 | 1.46 | Structure | Control Box | Crown | PG&E control box next to sidewalk on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 95 | 1.47 | 1.48 | Structure | Building | Water Side | House on the waterside shoulder. Entry Last Updated : 1/27/2021 | LEVEELOG 17945 | | |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|---------------|------------|---|-------------------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 101 | 1.47 | 1.47 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 427 | 1.47 | 1.47 | Structure | Control Box | Crown | PG&E control box on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 428 | 1.48 | 1.48 | Structure | Manhole Cover | Crown | Sanitary sewer manhole cover on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 96 | 1.48 | 1.50 | Structure | Building | Water Side | House on the waterside shoulder. Entry Last Updated : 1/27/2021 | LEVEELOG 17946 | | |
| 97 | 1.50 | 1.51 | Structure | Building | Water Side | House on the waterside shoulder. Entry Last Updated : 1/27/2021 | LEVEELOG 17947 | | |
| 429 | 1.50 | 1.50 | Structure | Control Box | Crown | PG&E control box on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 430 | 1.52 | 1.52 | Mark | Marker | Water Side | Small marker indicating levee mile 1.5 on waterside hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 431 | 1.52 | 1.52 | Structure | Mailbox | Crown | Community mailbox on water side of crown of levee by sidewalk. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 15 | 1.52 | 1.52 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 475 | 1.53 | 1.53 | Structure | Manhole Cover | Crown | Monitor manhole cover on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 432 | 1.54 | 1.54 | Structure | Control Box | Crown | Telecommunication and PG&E control boxes on the waterside of crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 433 | 1.55 | 1.55 | Structure | Manhole Cover | Crown | Sanitary sewer manhole cover on levee crown. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 436 | 1.56 | 1.56 | Structure | Control Box | Crown | Telecommunication control box on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 435 | 1.56 | 1.56 | Structure | Other | Land Side | Metal bench on concrete pad, located on landside toe of levee. Entry Last Updated : 3/17/2015 | LEVEELOG | | |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|---------------|-------------------------|---|---------------------|--------------|
| Unit No. 01 Sacramento River | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | |
| | Start | End | | | | | Permits | |
| 16 | 1.57 | 1.57 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | |
| 437 | 1.57 | 1.57 | Structure | Manhole Cover | Crown | Small manhole cover, labeled "monument" on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | |
| 438 | 1.59 | 1.59 | Structure | Manhole Cover | Crown | Sanitary sewer manhole cover located next to sidewalk on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | |
| 439 | 1.59 | 1.59 | Structure | Manhole Cover | Crown | Small manhole cover on crown of levee, labeled "monument". Entry Last Updated : 3/17/2015 | LEVEELOG | |
| 440 | 1.60 | 1.74 | Structure | Park | Land Side | Small park with picnic benches and accent lighting located near landside toe of levee, next to bike path. Entry Last Updated : 3/17/2015 | LEVEELOG | |
| 18 | 1.61 | 1.61 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | |
| 441 | 1.63 | 1.63 | Structure | Manhole Cover | Crown | Small manhole cover on crown, labeled "monument". Entry Last Updated : 3/17/2015 | LEVEELOG | |
| 102 | 1.66 | 1.66 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | |
| 442 | 1.68 | 1.68 | Structure | Mailbox | Crown | Community mailbox located next to sidewalk. Entry Last Updated : 3/17/2015 | LEVEELOG | |
| 443 | 1.69 | 1.69 | Structure | Control Box | Crown | Telecommunications control box located next to sidewalk on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | |
| 27 | 1.70 | 1.70 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | |
| 11 | 1.72 | 1.72 | UCIP | Conduit | Land Side to Water Side | DS_ID:261 EP_NO: 5528 Crossing Status: Not Found FIELD_STRUCT_DESC: 2-inch electrical conduit of an unknown material through the levee, 1.5 feet below the crown. Electrical conduit supplies power to an existing pumping plant located on the waterside (WS) slope of the levee. (2-inch conduit authorized under Permit No. 5528, 1966 - G.W. Williams Company) Entry Last Updated : 4/17/2021 | UCIPAPR2021 5528 | |

Flood Control Project Maintenance Levee Inspections

Levee Log Report By Levee Mile - Updated 8/23/2021

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | Bank | Unit Miles | Inspector |
|------------------------------|-------|------------|--------------|
| Unit No. 01 Sacramento River | Right | 3.47 | David Julian |

| Entry No | Levee Mile | | Category | Item | Location | Comment | Source |
|----------|------------|-----|----------|------|----------|---------|---------|
| | Start | End | | | | | Permits |

| | | | | | | | |
|-----|------|------|-----------|---------------|-----------|---|---------------------|
| 9 | 1.72 | 1.72 | UCIP | Pipe | Crossing | DS_ID:262 EP_NO: 5824 Crossing Status: Not Found FIELD_STRUCT_DESC: 8-inch welded steel, dipped and wrapped, discharge pipe, 8.2 feet below the crown. This pipe is a replacement for an existing 8-inch pipe. The new pipe was installed between the existing pumping plant located on the waterside (WS) berm of the levee and the existing reinforced concrete discharge box located at the landside (LS) toe, a distance of 88.5 feet. (Replaced an existing 8-inch welded steel pipe discharge line on an existing pumping plant authorized under Permit No. 5824, 1967 - G. W. Williams Company). [Additional Reference(s): USACE Sacramento O&M Manual, Unit 116, August 1955, Revised 29 Dec 2016, (RM 60.85), listed as 8-inch pipe]. Entry Last Updated : 4/17/2021 | UCIPAPR2021 5824 |
| 445 | 1.74 | 1.74 | Structure | Manhole Cover | Crown | Small manhole cover, labeled "monument" on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG |
| 446 | 1.74 | 1.74 | Structure | Manhole Cover | Crown | Small manhole cover, labeled "monument" on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG |
| 447 | 1.75 | 1.75 | Structure | Pipe Section | Land Side | Covered pipe and valve on landside toe. Entry Last Updated : 3/17/2015 | LEVEELOG |
| 449 | 1.76 | 1.76 | Structure | Control Box | Land Side | Water control box on landside toe. Entry Last Updated : 1/27/2021 | LEVEELOG |
| 448 | 1.76 | 1.76 | Structure | Control Box | Land Side | Pipes, pump, and control boxes located in a locked cage, on the landside toe. Entry Last Updated : 3/26/2015 | LEVEELOG |
| 28 | 1.76 | 1.76 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG |
| 450 | 1.79 | 1.79 | Structure | Other | Land Side | Metal bench on concrete pad on landside toe, next to bike path. Entry Last Updated : 3/17/2015 | LEVEELOG |
| 34 | 1.80 | 1.80 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG |
| 451 | 1.81 | 1.81 | Structure | Manhole Cover | Crown | Small manhole cover, labeled "monument" on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|---------------|------------|--|-----------------------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 40 | 1.84 | 1.84 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 453 | 1.85 | 1.85 | Structure | Mailbox | Crown | Community mailbox located next to sidewalk. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 454 | 1.87 | 1.87 | Structure | Manhole Cover | Crown | Small manhole cover, labeled "monument" on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 41 | 1.88 | 1.88 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 455 | 1.89 | 1.89 | Structure | Other | Crown | Metal bench on a concrete pad on crown of levee. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 457 | 1.89 | 1.89 | Structure | Manhole Cover | Crown | Small manhole cover, labeled "monument" on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 458 | 1.90 | 1.90 | Structure | Control Box | Crown | Telecommunication control box next to sidewalk on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 48 | 1.91 | 1.91 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 459 | 1.93 | 1.93 | Structure | Control Box | Crown | Telecommunication control box located next to sidewalk on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 112 | 1.93 | 1.93 | Aerial | High Voltage | Land Side | Overhead power line along the landside toe. Entry Last Updated : 1/27/2021 | USGSQUAD_EGIS 5509 | | |
| 460 | 1.94 | 1.96 | Structure | Pad | Water Side | Parking lot for a home sales office "The Rivers". Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 461 | 1.94 | 1.94 | Structure | Manhole Cover | Crown | Small manhole cover, labeled "monument" on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 462 | 1.96 | 1.96 | Structure | Control Box | Crown | Telecommunications and PG&E control boxes on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 463 | 1.96 | 1.96 | Structure | Sign | Water Side | Parking sign for the home sales office on the waterside. Entry Last Updated : 1/27/2021 | LEVEELOG | | |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|-----------------|------------|---|----------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 465 | 1.97 | 1.97 | Structure | Control Box | Crown | PG&E and sanitary sewer control boxes on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 464 | 1.97 | 1.97 | Structure | Building | Water Side | Home sales office for "The Rivers" on the waterside shoulder. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 468 | 1.97 | 1.97 | Ramp | Ramp | Land Side | Paved ramp is the continuation of River Crest Drive, which leads from the levee crown to Fountain Drive. Ramp has concrete sidewalks on both sides. Entry Last Updated : 3/26/2015 | LEVEELOG | | |
| 466 | 1.98 | 1.98 | Structure | Sign | Crown | Street sign at the intersection of River Crest Drive and the ramp that leads from the levee crown down to the adjacent road. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 467 | 1.98 | 1.98 | Structure | Manhole Cover | Crown | Small manhole cover, labeled "monument" on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 51 | 1.98 | 1.98 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 471 | 1.98 | 1.98 | Structure | Sign | Crown | Left arrow sign, next to sidewalk. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 472 | 1.98 | 1.98 | Structure | Sign | Land Side | Stop sign with road names at bottom of ramp, at the intersection of Fountain Drive and River Crest Drive. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 470 | 1.98 | 1.98 | Structure | Control Box | Crown | Pac-Bell control box on crown of levee, next to sidewalk. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 473 | 1.99 | 1.99 | Structure | Sign | Crown | Right arrow sign, located next to sidewalk. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 476 | 2.00 | 2.00 | Gate | Metal | Crown | Metal gate across the levee crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 477 | 2.00 | 2.00 | Structure | Monitoring Well | Land Side | Monitoring well by LS hinge. Entry Last Updated : 3/17/2015 | LEVEELOG | | |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | Bank | Unit Miles | Inspector |
|------------------------------|-------|------------|--------------|
| Unit No. 01 Sacramento River | Right | 3.47 | David Julian |

| Entry No | Levee Mile | | Category | Item | Location | Comment | Source |
|----------|------------|-----|----------|------|----------|---------|---------|
| | Start | End | | | | | Permits |

| | | | | | | | |
|-----|------|------|-----------|----------------|------------|---|-----------------------|
| 12 | 2.01 | 2.01 | UCIP | Pipe | Crossing | DS_ID:274 EP_NO: Crossing Status: Not Found FIELD_STRUCT_DESC: 12-inch steel irrigation pipe through the levee, at an unknown depth. [Additional Reference(s): USACE Sacramento O&M Manual, Unit 116, August 1955, Revised 29 Dec 2016, (RM 60.55), listed as 12-inch steel pipe]. Entry Last Updated : 4/17/2021 | UCIPAPR2021 |
| 478 | 2.02 | 2.02 | Mark | Marker | Water Side | LM 2.0 marker at WS hinge. Entry Last Updated : 3/17/2015 | LEVEELOG |
| 479 | 2.02 | 2.05 | Fence | Chain Link | Land Side | Chain link fence with wood slats at LS toe. Entry Last Updated : 3/17/2015 | LEVEELOG |
| 480 | 2.05 | 2.21 | Fence | Wrought Iron | Land Side | Wrought iron fence at LS toe. Entry Last Updated : 3/17/2015 | LEVEELOG |
| 481 | 2.06 | 2.70 | At Grade | Road / Highway | Crown | Levee crown is paved. Entry Last Updated : 3/17/2015 | LEVEELOG |
| 130 | 2.10 | 2.10 | Structure | Dock | Water Side | For dredging of an existing harbor, construction of boat docks, apartments, swimming pool, restaurant and cocktail lounge; In the overflow area on the right bank Sacramento River near Bryte Entry Last Updated : 3/11/2015 | USGSQUAD_EGIS 3883 |
| 482 | 2.10 | 2.10 | Ramp | Ramp | Water Side | Small paved ramp on WS leading to small dirt walking trail. Entry Last Updated : 3/17/2015 | LEVEELOG |
| 483 | 2.16 | 2.16 | Ramp | Ramp | Water Side | Paved ramp on WS with abandoned gate leading to paved open area. Entry Last Updated : 3/17/2015 | LEVEELOG |
| 484 | 2.17 | 2.17 | Structure | Pole | Land Side | Abandoned metal pole on LS near crown. Entry Last Updated : 3/17/2015 | LEVEELOG |
| 488 | 2.34 | 2.34 | Ramp | Ramp | Land Side | Paved ramp by LS toe. Entry Last Updated : 1/27/2021 | LEVEELOG |
| 489 | 2.34 | 2.34 | Structure | Manhole Cover | Land Side | Monument manhole cover near LS hinge. Entry Last Updated : 3/17/2015 | LEVEELOG |
| 490 | 2.35 | 2.35 | Structure | Sign | Crown | Stop sign at LS hinge. Entry Last Updated : 3/17/2015 | LEVEELOG |

Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|---------------|-----------------|------------|---|------------------------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 143 | 2.37 | 2.37 | Structure | Monitoring Well | N/A | Water well in the levee. Entry Last Updated : 1/27/2021 | USGSQUAD_EGIS 9279 | | |
| 491 | 2.41 | 2.41 | Structure | Pad | Water Side | Abandoned concrete pad on WS near crown. Entry Last Updated : 3/17/2015 | LEEVELOG | | |
| 13 | 2.41 | 2.41 | UCIP | Pipe | Crossing | DS_ID:264 EP_NO: 4561 Crossing Status: Not Found FIELD_STRUCT_DESC: 2-inch welded, wrapped steel high-pressure natural gas main through the levee, 2.5 feet below the crown. (2-inch welded, wrapped steel high-pressure natural gas main authorized under Permit No. 4561, 1964 - Pacific Gas and Electric Company [PG&E]). Entry Last Updated : 4/17/2021 | UCIPAPR2021 4561 | | |
| 494 | 2.43 | 2.60 | At Grade | Road / Highway | Land Side | Lighthouse Rd and sidewalk by LS toe. Entry Last Updated : 3/17/2015 | LEEVELOG | | |
| 492 | 2.44 | 2.44 | Structure | Pad | Water Side | Paved abandoned road on WS perpendicular to levee crown approx 100 ft long. Entry Last Updated : 3/17/2015 | LEEVELOG | | |
| 493 | 2.48 | 2.48 | Structure | Sign | Crown | Warning sign on WS hinge. Entry Last Updated : 3/17/2015 | LEEVELOG | | |
| 495 | 2.50 | 2.50 | Structure | Pole - Light | Land Side | Light pole at LS toe. Entry Last Updated : 3/17/2015 | LEEVELOG | | |
| 496 | 2.53 | 2.53 | Structure | Control Box | Land Side | Irrigation control box at LS toe. Entry Last Updated : 3/17/2015 | LEEVELOG | | |
| 497 | 2.54 | 2.54 | Ramp | Ramp | Land Side | Small dirt pedestrian ramp with two bollards on LS leading to Lighthouse Rd. Entry Last Updated : 3/17/2015 | LEEVELOG | | |
| 85 | 2.56 | 2.56 | Miscellaneous | Irrigation | Water Side | Irrigation on the waterward slope. Entry Last Updated : 1/27/2021 | LEEVELOG 10876 | | |
| 153 | 2.56 | 2.56 | Miscellaneous | Landscaping | Water Side | Landscape on the waterward slope of the levee and the overflow area. Entry Last Updated : 1/27/2021 | USGSQUAD_EGIS 10876 | | |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | Bank | Unit Miles | Inspector |
|------------------------------|-------|------------|--------------|
| Unit No. 01 Sacramento River | Right | 3.47 | David Julian |

| Entry No | Levee Mile | | Category | Item | Location | Comment | Source |
|----------|------------|-----|----------|------|----------|---------|---------|
| | Start | End | | | | | Permits |

| | | | | | | | |
|-----|------|------|-----------|----------------|------------|--|--------------------------|
| 19 | 2.59 | 2.59 | UCIP | Pipe | Crossing | DS_ID:254 EP_NO: Crossing Status: Not Found FIELD_STRUCT_DESC: 48-inch corrugated metal drainage pipe through the levee, 24.2 feet below the crown. Pipe has been grouted. [Additional Reference(s): DWR Levee Log, 2005 (HLM 2.56)]. Entry Last Updated : 4/17/2021 | UCIPAPR2021 |
| 160 | 2.66 | 2.66 | Structure | Pole - Utility | Land Side | High voltage pole on LS hinge. Entry Last Updated : 3/17/2015 | LEVEELOG |
| 161 | 2.66 | 2.66 | Gate | Metal | Crown | Pipe gate across levee crown with bollards on WS slope. Entry Last Updated : 3/17/2015 | USACEPI |
| 500 | 2.67 | 2.67 | Structure | Sign | Crown | Left arrow sign at LS hinge. Entry Last Updated : 3/17/2015 | LEVEELOG |
| 501 | 2.67 | 2.67 | Aerial | High Voltage | Crossing | High voltage and phone lines cross levee crown. Entry Last Updated : 3/17/2015 | LEVEELOG |
| 504 | 2.68 | 2.68 | Structure | Sign | Water Side | Sign by gate at bottom of WS paved ramp. Entry Last Updated : 3/17/2015 | LEVEELOG |
| 502 | 2.68 | 2.68 | Ramp | Ramp | Crossing | Paved ramp (App. No. 8651) crosses levee crown at 4th St and goes to paved parking area with bathroom and to boat harbor and launch facilities. (App. No. 5651). Metal pipe gate at bottom of WS ramp. Entry Last Updated : 3/25/2015 | LEVEELOG 5651 8651 |
| 503 | 2.68 | 2.68 | Structure | Sign | Water Side | River Walk sign by WS hinge. Entry Last Updated : 3/17/2015 | LEVEELOG |
| 506 | 2.69 | 2.69 | Aerial | High Voltage | Crossing | High voltage and phone lines cross levee crown again. Entry Last Updated : 3/26/2015 | LEVEELOG |
| 505 | 2.69 | 2.69 | Structure | Building | Land Side | House by paved LS ramp. Entry Last Updated : 3/17/2015 | LEVEELOG |
| 507 | 2.69 | 2.69 | Structure | Control Box | Water Side | Telephone control box on WS near levee crown. Entry Last Updated : 3/17/2015 | LEVEELOG |

Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | Bank | Unit Miles | Inspector |
|------------------------------|-------|------------|--------------|
| Unit No. 01 Sacramento River | Right | 3.47 | David Julian |

| Entry No | Levee Mile | | Category | Item | Location | Comment | Source |
|----------|------------|-----|----------|------|----------|---------|---------|
| | Start | End | | | | | Permits |

| | | | | | | | |
|----|------|------|------|------|------------|--|-------------|
| 20 | 2.69 | 2.69 | UCIP | Pipe | Water Side | DS_ID:19405 EP_NO: Crossing Status: Found FIELD_STRUCT_DESC: 6-inch steel sewer line from the public facility of the boat launching area. No other details available. Entry Last Updated : 4/17/2021 | UCIPAPR2021 |
|----|------|------|------|------|------------|--|-------------|

| | | | | | | | |
|-----|------|------|------|-------|-------|--|----------|
| 510 | 2.69 | 2.69 | Gate | Metal | Crown | Metal gate across the levee crown. Entry Last Updated : 1/27/2021 | LEVEELOG |
|-----|------|------|------|-------|-------|--|----------|

| | | | | | | | |
|-----|------|------|-----------|---------------|-----------|--|---------|
| 171 | 2.70 | 2.70 | Structure | Manhole Cover | Land Side | Sewer manhole cover at LS toe. Entry Last Updated : 1/27/2021 | USACEPI |
|-----|------|------|-----------|---------------|-----------|--|---------|

| | | | | | | | |
|-----|------|------|-----------|------|-------|---|----------|
| 508 | 2.70 | 2.70 | Structure | Sign | Crown | Warning sign at LS hinge. Entry Last Updated : 3/17/2015 | LEVEELOG |
|-----|------|------|-----------|------|-------|---|----------|

| | | | | | | | |
|-----|------|------|------|------|------------|---|----------|
| 509 | 2.70 | 2.70 | Ramp | Ramp | Water Side | Small paved ramp with bollards on WS leading to Parking area. Entry Last Updated : 3/26/2015 | LEVEELOG |
|-----|------|------|------|------|------------|---|----------|

| | | | | | | | |
|-----|------|------|-----------|---------------|------------|--|----------|
| 511 | 2.70 | 2.70 | Structure | Manhole Cover | Water Side | Sewer manhole cover by WS toe. Entry Last Updated : 3/17/2015 | LEVEELOG |
|-----|------|------|-----------|---------------|------------|--|----------|

| | | | | | | | |
|-----|------|------|-----------|-----|------------|---|---------------------------|
| 513 | 2.70 | 2.75 | Structure | Pad | Water Side | Paved parking lot on WS for boating facilities. Entry Last Updated : 3/25/2015 | LEVEELOG 17551 3002 |
|-----|------|------|-----------|-----|------------|---|---------------------------|

| | | | | | | | |
|-----|------|------|-------|--------------|-----------|--|----------|
| 514 | 2.70 | 2.76 | Fence | Wrought Iron | Land Side | Wrought iron fence by LS toe contains water tank and pump station. Entry Last Updated : 3/26/2015 | LEVEELOG |
|-----|------|------|-------|--------------|-----------|--|----------|

| | | | | | | | |
|-----|------|------|-----------|----------|------------|--|----------|
| 512 | 2.71 | 2.71 | Structure | Building | Water Side | Metal storage structure by WS toe. Entry Last Updated : 1/27/2021 | LEVEELOG |
|-----|------|------|-----------|----------|------------|--|----------|

| | | | | | | | |
|-----|------|------|-----------|------|-----------|--|-----------------|
| 177 | 2.71 | 2.71 | Structure | Tank | Land Side | Water tank and 4 approx 1-ft steel pipes each with a pump. Entry Last Updated : 1/27/2021 | USACEPI 3781 |
|-----|------|------|-----------|------|-----------|--|-----------------|

| | | | | | | | |
|-----|------|------|-----------|--------------|-----------|--|---------|
| 174 | 2.75 | 2.75 | Structure | Pump Station | Land Side | Pump station with utility boxes behind wrought iron fence by LS toe. Entry Last Updated : 3/17/2015 | USACEPI |
|-----|------|------|-----------|--------------|-----------|--|---------|

Flood Control Project Maintenance Levee Inspections

Levee Log Report By Levee Mile - Updated 8/23/2021

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | Bank | Unit Miles | Inspector |
|------------------------------|-------|------------|--------------|
| Unit No. 01 Sacramento River | Right | 3.47 | David Julian |

| Entry No | Levee Mile | | Category | Item | Location | Comment | Source |
|----------|------------|-----|----------|------|----------|---------|---------|
| | Start | End | | | | | Permits |

| | | | | | | | |
|----|------|------|------|------|----------|---|----------------------|
| 21 | 2.75 | 2.75 | UCIP | Pipe | Crossing | DS_ID:255 EP_NO: 14903 Crossing Status: Found FIELD_STRUCT_DESC: [Lighthouse Marina Drainage Pump Station] 1 of 5: 42-inch coated steel drainage pipe through the levee, 2.2 feet below the crown, in a storm pump station consisting of two 42-inch, two 30-inch, and one 10-inch pipes through the levee. System is connected to a 72-inch outfall structure in the right bank overflow area of the Sacramento River. Levee raised to obtain required cover over pipes. (two 42-inch, two 30-inch, and one 10-inch discharge pipes and storm pump station authorized under Permit No. 14903, 1988 - City of West Sacramento). [Additional Reference(s): DWR Levee Log, 2005 (HLM 2.71)]. Entry Last Updated : 4/17/2021 | UCIPAPR2021 14903 |
|----|------|------|------|------|----------|---|----------------------|

| | | | | | | | |
|----|------|------|------|------|----------|--|----------------------|
| 22 | 2.75 | 2.75 | UCIP | Pipe | Crossing | DS_ID:483 EP_NO: 14903 Crossing Status: Found FIELD_STRUCT_DESC: [Lighthouse Marina Drainage Pump Station] 2 of 5: 30-inch coated steel drainage pipe through the levee, 3.2 ft. below the crown, in a storm pump station consisting of two 42-inch, two 30-inch, and one 10-inch pipes through the levee. System is connected to a 72-inch outfall structure in the right bank overflow area of the Sacramento River. Levee raised to obtain required cover over pipes. (two 42-inch, two 30-inch, and one 10-inch discharge pipes and storm pump station authorized under Permit No. 14903, 1988 - City of West Sacramento). [Additional Reference(s): DWR Levee Log, 2005 (HLM 2.71)]. Entry Last Updated : 4/17/2021 | UCIPAPR2021 14903 |
|----|------|------|------|------|----------|--|----------------------|

| | | | | | | | |
|----|------|------|------|------|----------|---|----------------------|
| 23 | 2.75 | 2.75 | UCIP | Pipe | Crossing | DS_ID:484 EP_NO: 14903 Crossing Status: Found FIELD_STRUCT_DESC: [Lighthouse Marina Drainage Pump Station] 3 of 5: 10-inch coated steel drainage pipe through the levee, 2.2 feet below the crown, in a storm pump station consisting of two 42-inch, two 30-inch, and one 10-inch pipes through the levee. System is connected to a 72-inch outfall structure in the right bank overflow area of the Sacramento River. Levee raised to obtain required cover over pipes. (two 42-inch, two 30-inch, and one 10-inch discharge pipes and storm pump station authorized under Permit No. 14903, 1988 - City of West Sacramento). [Additional Reference(s): DWR Levee Log, 2005 (HLM 2.71)]. Entry Last Updated : 4/17/2021 | UCIPAPR2021 14903 |
|----|------|------|------|------|----------|---|----------------------|

Flood Control Project Maintenance Levee Inspections

Levee Log Report By Levee Mile - Updated 8/23/2021

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | Bank | Unit Miles | Inspector |
|------------------------------|-------|------------|--------------|
| Unit No. 01 Sacramento River | Right | 3.47 | David Julian |

| Entry No | Levee Mile | | Category | Item | Location | Comment | Source |
|----------|------------|-----|----------|------|----------|---------|---------|
| | Start | End | | | | | Permits |

| | | | | | | | |
|----|------|------|------|------|----------|---|----------------------|
| 25 | 2.75 | 2.75 | UCIP | Pipe | Crossing | DS_ID:485 EP_NO: 14903 Crossing Status: Found FIELD_STRUCT_DESC: [Lighthouse Marina Drainage Pump Station] 4 of 5: 30-inch coated steel drainage pipe through the levee, 3.2 feet below the crown, in a storm pump station consisting of two 42-inch, two 30-inch, and one 10-inch pipes through the levee. System is connected to a 72-inch outfall structure in the right bank overflow area of the Sacramento River. Levee raised to obtain required cover over pipes. (two 42-inch, two 30-inch, and one 10-inch discharge pipes and storm pump station authorized under Permit No. 14903, 1988 - City of West Sacramento). [Additional Reference(s): DWR Levee Log, 2005 (HLM 2.71)]. Entry Last Updated : 4/17/2021 | UCIPAPR2021 14903 |
|----|------|------|------|------|----------|---|----------------------|

| | | | | | | | |
|----|------|------|------|------|----------|---|----------------------|
| 26 | 2.76 | 2.76 | UCIP | Pipe | Crossing | DS_ID:486 EP_NO: 14903 Crossing Status: Found FIELD_STRUCT_DESC: [Lighthouse Marina Drainage Pump Station] 5 of 5: 42-inch coated steel drainage pipe through the levee, 2.2 feet below the crown, in a storm pump station consisting of two 42-inch, two 30-inch, and one 10-inch pipes through the levee. System is connected to a 72-inch outfall structure in the right bank overflow area of the Sacramento River. Levee raised to obtain required cover over pipes. (two 42-inch, two 30-inch, and one 10-inch discharge pipes and storm pump station authorized under Permit No. 14903, 1988 - City of West Sacramento). [Additional Reference(s): DWR Levee Log, 2005 (HLM 2.71)]. Entry Last Updated : 4/17/2021 | UCIPAPR2021 14903 |
|----|------|------|------|------|----------|---|----------------------|

| | | | | | | | |
|-----|------|------|-----------|-------|-----------|---|--------------|
| 181 | 2.76 | 2.76 | Structure | Tower | Land Side | River Walk steel tower at LS toe with metal shed underneath and surrounded by cyclone fence with wood slats.. Entry Last Updated : 3/17/2015 | H_LL_GENERAL |
|-----|------|------|-----------|-------|-----------|---|--------------|

| | | | | | | | |
|-----|------|------|--------|--------------|-----------|---|----------|
| 520 | 2.77 | 2.82 | Aerial | High Voltage | Land Side | High voltage line along B Street at LS toe. Entry Last Updated : 3/17/2015 | LEVEELOG |
|-----|------|------|--------|--------------|-----------|---|----------|

| | | | | | | | |
|-----|------|------|----------|----------------|-----------|---|----------|
| 519 | 2.77 | 2.82 | At Grade | Road / Highway | Land Side | B Street at LS toe. Entry Last Updated : 3/17/2015 | LEVEELOG |
|-----|------|------|----------|----------------|-----------|---|----------|

| | | | | | | | |
|-----|------|------|-----------|--------------|------------|---|----------|
| 518 | 2.78 | 2.78 | Structure | Pipe Section | Water Side | Valve for petroleum pipeline enclosed by bollards and horizontal metal poles. Entry Last Updated : 3/17/2015 | LEVEELOG |
|-----|------|------|-----------|--------------|------------|---|----------|

| | | | | | | | |
|-----|------|------|-----------|--------------|------------|---|----------|
| 517 | 2.78 | 2.78 | Structure | Pipe Section | Water Side | Steel pipe and valve enclosed by chain link cage with bollards on WS. Entry Last Updated : 3/17/2015 | LEVEELOG |
|-----|------|------|-----------|--------------|------------|---|----------|

Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|-----------|------------|---|------------------------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 515 | 2.78 | 2.78 | Ramp | Ramp | Crossing | Small paved ramp crosses from intersection of B and 3rd Streets to parking lot on WS. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 516 | 2.78 | 2.78 | Gate | Metal | Land Side | Metal pipe gate on paved ramp by LS hinge. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 30 | 2.78 | 2.78 | UCIP | Pipe | Crossing | DS_ID:19406 EP_NO: Crossing Status: Found FIELD_STRUCT_DESC: 1 of 2: 3-inch wrapped galvanized iron (GI) water pipe through the levee, at an unknown depth. Pipe daylights in a metal cage box. Valve box for the pipe is also found. Entry Last Updated : 4/17/2021 | UCIPAPR2021 | | |
| 31 | 2.78 | 2.78 | UCIP | Pipe | Crossing | DS_ID:19407 EP_NO: Crossing Status: Found FIELD_STRUCT_DESC: 2 of 2: 5-inch wrapped galvanized iron (GI) water pipe through the levee, at an unknown depth. Pipe daylights in a metal cage box. Valve box for the pipe is also found. Entry Last Updated : 4/17/2021 | UCIPAPR2021 | | |
| 29 | 2.78 | 2.78 | UCIP | Pipe | Crossing | DS_ID:265 EP_NO: 14527 Crossing Status: Indicator Found FIELD_STRUCT_DESC: 12-inch coated steel petroleum pipeline, 3 feet below the crown. Gas/petroleum line markers found on both sides of the levee. (12.75-inch welded steel pipeline authorized under Permit No. 14527, 1987 - Southern Pacific Pipe Lines, Inc.). Entry Last Updated : 4/17/2021 | UCIPAPR2021 14527 | | |
| 521 | 2.78 | 2.78 | Structure | Sign | Land Side | Sign on B Street by LS toe. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 254 | 2.81 | 2.81 | Structure | Boat Ramp | Water Side | Broderick boat launching facility with concrete at the head of launching ramp. Entry Last Updated : 1/27/2021 | USGSQUAD_EGIS 17551 | | |
| | | | | | | replace asphalt;construct sidewalk;place riprap; w. sacramento Entry Last Updated : 3/11/2015 | 17551 | | |
| 522 | 2.81 | 2.81 | Structure | Sign | Land Side | Dead End sign by LS toe. Entry Last Updated : 3/17/2015 | LEVEELOG | | |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|----------------|------------|---|-------------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 523 | 2.82 | 2.82 | Ramp | Ramp | Water Side | Gravel ramp to WS toe road. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 525 | 2.82 | 2.85 | Aerial | Communications | Land Side | Possible abandoned phone line by LS toe. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 524 | 2.82 | 2.82 | Ramp | Ramp | Land Side | Paved ramp on LS to B Street. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 526 | 2.83 | 2.83 | Structure | Sign | Crown | Two signs on metal pole on levee crown. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 528 | 2.85 | 2.85 | Structure | Building | Land Side | L-shaped building by LS toe and along paved LS ramp. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 527 | 2.85 | 2.85 | Structure | Sign | Crown | Sign at LS hinge at top of paved ramp to B Street. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 530 | 2.86 | 2.86 | Ramp | Ramp | Land Side | Paved ramp on the landside slope. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 529 | 2.86 | 2.86 | Structure | Sign | Crown | Warning sign at WS hinge. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 531 | 2.86 | 2.86 | Gate | Metal | Land Side | Metal pipe gate at top of paved LS ramp. Entry Last Updated : 3/17/2015 | LEVEELOG | | |
| 32 | 2.91 | 2.91 | UCIP | Pipe | Crossing | DS_ID:18884 EP_NO: Crossing Status: Not Found FIELD_STRUCT_DESC: 1 of 4: 3-inch pipe of an unknown material or purpose through the levee, 18.6 feet below the crown. Pipe exposed and extends 10 feet from the bank and 5 feet above current water surface. Needs to be removed or grouted. [Additional Reference(s): DWR Levee Log, 2005 (HLM 2.88). USACE Sacramento O&M Manual, Unit 116, August 1955, Revised 29 Dec 2016, (RM 59.65), listed as one 3-inch, one 10-inch steel, and two 7-inch pipes; no USACE As-Built Drawing found for these pipes] Entry Last Updated : 4/17/2021 | UCIPAPR2021 | | |
| 532 | 2.92 | 2.95 | Fence | Chain Link | Land Side | Chain linke fence with wood slats and barbed wire runs up the bank halfway to the crown, then runs downriver. Fence encloses large water tank. Entry Last Updated : 3/18/2015 | LEVEELOG | | |

Flood Control Project Maintenance Levee Inspections

Levee Log Report By Levee Mile - Updated 8/23/2021

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | Bank | Unit Miles | Inspector |
|------------------------------|-------|------------|--------------|
| Unit No. 01 Sacramento River | Right | 3.47 | David Julian |

| Entry No | Levee Mile | | Category | Item | Location | Comment | Source |
|----------|------------|-----|----------|------|----------|---------|---------|
| | Start | End | | | | | Permits |

| | | | | | | | |
|----|------|------|------|------|----------|--|-------------|
| 35 | 2.93 | 2.93 | UCIP | Pipe | Crossing | DS_ID:18886 EP_NO: Crossing Status: Found FIELD_STRUCT_DESC: 2 of 4: 10-inch pipe of an unknown material or purpose through the levee, 18.6 feet below the crown. Pipe exposed and extends 10 feet from the bank and 5 feet above current water surface. Needs to be removed or grouted. [Additional Reference(s): DWR Levee Log, 2005 (HLM 2.88). USACE Sacramento O&M Manual 116, August 1955, (RM 59.65), listed as one 3-inch, one 10-inch steel, and two 7-inch pipes; no USACE As-Built Drawing found for these pipes]. Entry Last Updated : 4/17/2021 | UCIPAPR2021 |
|----|------|------|------|------|----------|--|-------------|

| | | | | | | | |
|----|------|------|------|------|----------|--|-------------|
| 33 | 2.93 | 2.93 | UCIP | Pipe | Crossing | DS_ID:18885 EP_NO: Crossing Status: Found FIELD_STRUCT_DESC: 4 of 4: 7-inch pipe of an unknown material or purpose through the levee, 18.6 feet below the crown. Unable to locate. Pipe exposed and extends 10 feet from the bank and 5 feet above current water surface. Needs to be removed or grouted. [Additional Reference(s): DWR Levee Log, 2005 (HLM 2.88). USACE Sacramento O&M Manual, Unit 116, August 1955, Revised 29 Dec 2016, (RM 59.65), listed as one 3-inch, one 10-inch steel, and two 7-inch pipes; no USACE As-Built Drawing found for these pipes]. Entry Last Updated : 4/17/2021 | UCIPAPR2021 |
|----|------|------|------|------|----------|--|-------------|

| | | | | | | | |
|----|------|------|------|------|----------|--|-------------|
| 36 | 2.93 | 2.93 | UCIP | Pipe | Crossing | DS_ID:18883 EP_NO: Crossing Status: Found FIELD_STRUCT_DESC: 3 of 4: 7-inch pipe of an unknown material or purpose through the levee, 18.6 feet below the crown. Unable to locate. Pipe exposed and extends 10 feet from the bank and 5 feet above current water surface. Needs to be removed or grouted. [Additional Reference(s): DWR Levee Log, 2005 (HLM 2.88). USACE Sacramento O&M Manual, Unit 116, August 1955, Revised 29 Dec 2016, (RM 59.65), listed as one 3-inch, one 10-inch steel, and two 7-inch pipes; no USACE As-Built Drawing found for these pipes]. Entry Last Updated : 4/17/2021 | UCIPAPR2021 |
|----|------|------|------|------|----------|--|-------------|

| | | | | | | | |
|-----|------|------|-----------|-----|------------|---|-----------------------|
| 196 | 2.93 | 2.93 | Structure | Pad | Water Side | Earthfill pad on the waterside slope. Entry Last Updated : 1/27/2021 | USGSQUAD_EGIS 4557 |
|-----|------|------|-----------|-----|------------|---|-----------------------|

| | | | | | | | |
|-----|------|------|-----------|--------------|-------|--|---------|
| 200 | 2.95 | 2.95 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | USACEPI |
|-----|------|------|-----------|--------------|-------|--|---------|

Flood Control Project Maintenance Levee Inspections

Levee Log Report By Levee Mile - Updated 8/23/2021

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|--|--|--|--|--|-------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | Right | 3.47 | David Julian |

| Entry No | Levee Mile | | Category | Item | Location | Comment | Source |
|----------|------------|-----|----------|------|----------|---------|---------|
| | Start | End | | | | | Permits |

| | | | | | | | |
|-----|------|------|-----------|----------------|------------|---|-----------------------|
| 37 | 2.99 | 2.99 | UCIP | Pipe | Crossing | DS_ID:266 EP_NO: 16702 Crossing Status: Not Found FIELD_STRUCT_DESC: 4.5-inch polyvinyl chloride (PVC) irrigation pipe through the levee, 2 feet below the crown. Public facilities and four stairways on the levee slope. Observation/fishing dock on the waterside (WS) of the levee. (4-inch irrigation pipe and 1-inch potable water main line authorized under Permit No. 16702, 1997 - City of West Sacramento). Entry Last Updated : 4/17/2021 | UCIPAPR2021 16702 |
| 533 | 3.02 | 3.02 | Ramp | Ramp | Water Side | Short gravel ramp leading from levee crown to water side. Entry Last Updated : 3/18/2015 | LEVEELOG |
| 192 | 3.02 | 3.02 | Structure | Sign | Crown | Small white sign indicating levee mile 3.0, located on water side hinge. Entry Last Updated : 3/18/2015 | LEVEELOG |
| 52 | 3.05 | 3.05 | Structure | Pole - Utility | Water Side | Powerline pole on the waterside slope. Entry Last Updated : 1/27/2021 | LEVEELOG |
| 535 | 3.05 | 3.05 | Structure | Sign | Water Side | Warning sign located on water side hinge. Entry Last Updated : 3/18/2015 | LEVEELOG |
| 534 | 3.05 | 3.05 | Aerial | High Voltage | Crossing | Overhead powerline crosses levee crown. Entry Last Updated : 1/27/2021 | LEVEELOG |
| 536 | 3.05 | 3.05 | Fence | Metal | Crossing | Metal fence running from landside over the levee crown to the waterside. Fence is on both sides of the RR tracks/bridge. Large boulders are located downstream of the RR tracks along the levee crest to limit access. Entry Last Updated : 3/18/2015 | LEVEELOG |
| 208 | 3.06 | 3.06 | Aerial | Bridge | Crossing | "I" Street Bridge for vehicular traffic crosses levee overhead. Entry Last Updated : 3/18/2015 | H_LL_GENERAL 16831 |
| 537 | 3.06 | 3.06 | At Grade | Railroad | Crossing | Southern Pacific RR tracks cross levee crown at grade. Entry Last Updated : 3/18/2015 | LEVEELOG |
| 540 | 3.08 | 3.08 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG |
| 81 | 3.08 | 3.45 | Structure | Other | Crown | Concrete pillars are located on waterside hinge approximately every 60 feet. Entry Last Updated : 8/25/2020 | LEVEELOG |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|---------------|-----------------|------------|--|-------------------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 543 | 3.08 | 3.47 | Miscellaneous | Landscaping | Water Side | Irrigated landscaping, grass, plants on the waterside slope. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 541 | 3.08 | 3.47 | At Grade | Bikepath | Water Side | Concrete walkway/bikepath running along water side toe. Entry Last Updated : 3/26/2015 | LEVEELOG | | |
| 539 | 3.08 | 3.08 | Structure | Stairs | Water Side | Concrete stair set with metal railings leads from levee crown to concrete walkway/bikepath at the waterside levee toe. Entry Last Updated : 3/26/2015 | LEVEELOG | | |
| 542 | 3.08 | 3.46 | At Grade | Road / Highway | Crown | West Sacramento riverfront improvements including 2200-ft promenade of paved levee crown (concrete and pavers). Entry Last Updated : 3/25/2015 | LEVEELOG 16702 | | |
| 538 | 3.08 | 3.08 | Ramp | Ramp | Land Side | Leads from road to levee crown, access limited by large boulders. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 54 | 3.09 | 3.09 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 24 | 3.09 | 3.09 | Structure | Sign | Water Side | Sign by the intersection of the ramp and the bike path. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 545 | 3.09 | 3.09 | Structure | Sign | Water Side | Sign by the intersection of the ramp and the bike path. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 544 | 3.09 | 3.14 | Ramp | Ramp | Water Side | Colored concrete paved ramp leading from the bike path up to the levee crown, possibly 8 feet wide. Entry Last Updated : 3/26/2015 | LEVEELOG | | |
| 546 | 3.10 | 3.10 | Structure | Other | Crown | Metal bench on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 53 | 3.10 | 3.10 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 547 | 3.10 | 3.10 | Structure | Monitoring Well | Crown | Monitoring well on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 548 | 3.10 | 3.10 | Structure | Other | Water Side | Metal bench located along concrete bike path. Entry Last Updated : 3/18/2015 | LEVEELOG | | |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|---------------|-----------------|------------|---|---------------------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 549 | 3.11 | 3.11 | Structure | Other | Crown | Metal bench on the crown. Entry Last Updated : 1/27/2021 | LEEVELOG | | |
| 550 | 3.11 | 3.11 | Structure | Monitoring Well | Crown | Monitoring well on the crown. Entry Last Updated : 1/27/2021 | LEEVELOG | | |
| 55 | 3.11 | 3.11 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEEVELOG | | |
| 551 | 3.11 | 3.11 | Structure | Other | Crown | Metal bike rack on the crown. Entry Last Updated : 1/27/2021 | LEEVELOG | | |
| 56 | 3.12 | 3.12 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEEVELOG | | |
| 554 | 3.12 | 3.14 | Ramp | Ramp | Land Side | Concrete pedestrian ramp with flowers and railings. Entry Last Updated : 1/27/2021 | LEEVELOG | | |
| 555 | 3.12 | 3.14 | Fence | Chain Link | Crown | Large anchor style chain with small metal poles, spaced between two light poles. Entry Last Updated : 3/18/2015 | LEEVELOG | | |
| 553 | 3.13 | 3.13 | Structure | Pole | Crown | Short metal pole at top of ramp, no sign. Entry Last Updated : 3/18/2015 | LEEVELOG | | |
| 557 | 3.14 | 3.37 | Miscellaneous | Landscaping | Land Side | Irrigated landscaping with plants, trees on the landside slope. Entry Last Updated : 1/27/2021 | LEEVELOG | | |
| 57 | 3.14 | 3.14 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEEVELOG | | |
| 38 | 3.14 | 3.14 | UCIP | Conduit | Crossing | DS_ID:256 EP_NO: 2075 Crossing Status: Indicator Found FIELD_STRUCT_DESC: 2-inch armored submarine telephone conduit of an unknown material through the levee, 5 feet below the crown. (Armored submarine cable authorized under Permit No. 2075, 1955 - Pacific Telephone and Telegraph Company [PT&T]). [Additional Reference(s): DWR Levee Log, 2005 (HLM 3.10)]. Entry Last Updated : 4/17/2021 | UCIPAPR2021 2075 | | |
| 556 | 3.14 | 3.14 | Structure | Sign | Water Side | Wheelchair accessible sign located at top of ramp. Entry Last Updated : 3/18/2015 | LEEVELOG | | |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|------------|------------|--|---------------------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 39 | 3.14 | 3.14 | UCIP | Conduit | Crossing | DS_ID:257 EP_NO: 7107 Crossing Status: Indicator Found FIELD_STRUCT_DESC: Twenty 4-inch fiberglass submarine telephone conduits through the levee, 5 feet below the crown. Specially designed cutoff walls. (Submarine telephone cable authorized under Permit No. 7107, 1972 - Pacific Telephone and Telegraph Company [PT&T]). [Additional Reference(s): DWR Levee Log, 2005 (HLM 3.10)]. Entry Last Updated : 4/17/2021 | UCIPAPR2021 7107 | | |
| 105 | 3.14 | 3.14 | UCIP | Pipe | | DS_ID:269 EP_NO: 2075 Crossing Status: Indicator Found FIELD_STRUCT_DESC: Installation and maintenance of an armored submarine telephone conduit of an unknown size or material across the channel of the Sacramento River and its levees, at an unknown depth. (Armored submarine cable authorized under Permit No. 2075, 1955 - Pacific Telephone and Telegraph Company [PT&T]). Entry Last Updated : 4/17/2021 | UCIPAPR2021 2075 | | |
| 558 | 3.14 | 3.14 | Structure | Building | Crown | Restroom building on the crown. Entry Last Updated : 1/27/2021 | LEEVELOG | | |
| 561 | 3.15 | 3.15 | Structure | Sign | Water Side | Wood sign with three wood poles at water side toe, next to concrete bike path. Entry Last Updated : 3/18/2015 | LEEVELOG | | |
| 562 | 3.15 | 3.15 | Structure | Sign | Water Side | Small sign on water side hinge. Entry Last Updated : 3/18/2015 | LEEVELOG | | |
| 559 | 3.15 | 3.15 | Ramp | Ramp | Land Side | Ramp leads from crown to E Street. Entry Last Updated : 1/27/2021 | LEEVELOG | | |
| 564 | 3.15 | 3.17 | Fence | Chain Link | Crown | Large anchor style chain with small metal poles, spaced between two light poles. Entry Last Updated : 3/18/2015 | LEEVELOG | | |
| 563 | 3.15 | 3.20 | Ramp | Ramp | Water Side | Asphalt ramp leads from crown to concrete bike path. Entry Last Updated : 3/26/2015 | LEEVELOG | | |
| 566 | 3.16 | 3.16 | Structure | Other | Crown | Metal bench on the crown. Entry Last Updated : 1/27/2021 | LEEVELOG | | |
| 565 | 3.16 | 3.19 | Structure | Building | Land Side | CALSTRS building on the landside toe. Entry Last Updated : 1/27/2021 | LEEVELOG | | |

Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|--------------|-----------|--|----------------------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 59 | 3.17 | 3.17 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 567 | 3.18 | 3.18 | Structure | Other | Crown | Metal bench on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 60 | 3.18 | 3.18 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 568 | 3.18 | 3.18 | Structure | Sign | Crown | River Walk display on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 569 | 3.18 | 3.18 | Structure | Other | Crown | Metal bench on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 61 | 3.19 | 3.19 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 570 | 3.19 | 3.19 | Structure | Sign | Crown | River Walk display on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 42 | 3.20 | 3.20 | UCIP | Conduit | Crossing | DS_ID:268 EP_NO: 17058 Crossing Status: Not Found FIELD_STRUCT_DESC: Three 2-inch and two 1.5-inch fiber optics conduits of an unknown material across and bored under the Sacramento River and its west levee. Note in permit indicates this was not installed. Entry Last Updated : 4/17/2021 | UCIPAPR2021 17058 | | |
| 572 | 3.20 | 3.20 | Structure | Sign | Crown | River Walk display on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 571 | 3.20 | 3.20 | Ramp | Ramp | Land Side | Ramp with pavers towards 3rd Steet, with metal bike locks. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 62 | 3.20 | 3.20 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 573 | 3.20 | 3.22 | Fence | Chain Link | Crown | Large anchor style chain with small metal poles, spaced between two light poles. Entry Last Updated : 3/18/2015 | LEVEELOG | | |

Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|-------------------------|-------------------------|---|----------------------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 574 | 3.21 | 3.21 | Structure | Other | Crown | Metal bench on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 576 | 3.21 | 3.21 | At Grade | Road / Highway | Land Side | Road provides access to the CALSTRS building. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 577 | 3.22 | 3.22 | Wall | Concrete / Masonry Wall | Land Side | Concrete planter box on the landside slope. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 579 | 3.22 | 3.24 | Structure | Pole | Crown | Light poles and flag poles. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 578 | 3.22 | 3.24 | Structure | Stairs | Water Side | Concrete stairs on the waterside slope. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 581 | 3.24 | 3.24 | Wall | Concrete / Masonry Wall | Land Side | Concrete planter on the landside slope. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 580 | 3.24 | 3.24 | Structure | Stairs | Land Side | Concrete stairs with railings leading from crown to E Street. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 43 | 3.24 | 3.24 | UCIP | Pipe | Land Side to Water Side | DS_ID:258 EP_NO: 14854 Crossing Status: Found FIELD_STRUCT_DESC: 36-inch coated steel storm water drainage pipe through the levee, 3.5 ft. below the crown. Concrete headwall and flap gate at the riverbank. Siphon breaker at the landside (LS) shoulder. (Relocation of a force main storm drain outfall structure authorized under Permit No. 14854, 1988 - Raley's Landing, Inc.) [Additional Reference(s): DWR Levee Log, 2005 (HLM 3.24)]. Entry Last Updated : 4/17/2021 | UCIPAPR2021 14854 | | |
| 582 | 3.24 | 3.26 | Fence | Chain Link | Crown | Large anchor style chain with small metal poles, spaced between two light poles. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 583 | 3.24 | 3.24 | Structure | Control Box | Water Side | Utility box at WS hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |

Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | Bank | Unit Miles | Inspector |
|------------------------------|-------|------------|--------------|
| Unit No. 01 Sacramento River | Right | 3.47 | David Julian |

| Entry No | Levee Mile | | Category | Item | Location | Comment | Source |
|----------|------------|-----|----------|------|----------|---------|---------|
| | Start | End | | | | | Permits |

| | | | | | | | |
|-----|------|------|-----------|--------------|-------------------------|---|---------------------|
| 44 | 3.25 | 3.25 | UCIP | Pipe | Land Side to Water Side | DS_ID:270 EP_NO: 4668 Crossing Status: Not Found FIELD_STRUCT_DESC: *ABANDONED w/ Permit* 30-inch coated steel storm water discharge pipe through the levee, 6 feet below the crown. Concrete headwall on the waterside (WS). Pumping plant on the landside (LS). (36-inch reinforced concrete discharge pipe and storm water pumping plant authorized under Permit No. 4668, 1964 - County of Yolo, Department of Public Works. 36-inch pipe was properly abandoned under Permit No. 14854, 1988 - Raley's Landing, Inc.) Entry Last Updated : 4/17/2021 | UCIPAPR2021 4668 |
| 585 | 3.25 | 3.30 | Fence | Chain Link | Land Side | Chain link fence at LS hinge. Entry Last Updated : 3/18/2015 | LEVEELOG |
| 584 | 3.25 | 3.25 | Structure | Control Box | Land Side | Large green locked cmp standpipe containing valves. Entry Last Updated : 3/18/2015 | LEVEELOG |
| 63 | 3.26 | 3.26 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG |
| 586 | 3.26 | 3.26 | Structure | Other | Land Side | Bench on the landside hinge. Entry Last Updated : 1/27/2021 | LEVEELOG |
| 64 | 3.27 | 3.27 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG |
| 588 | 3.27 | 3.27 | Structure | Other | Land Side | Bench on the landside hinge. Entry Last Updated : 1/27/2021 | LEVEELOG |
| 587 | 3.27 | 3.27 | Structure | Sign | Water Side | River Walk display at WS hinge. Entry Last Updated : 3/18/2015 | LEVEELOG |
| 591 | 3.27 | 3.30 | Fence | Chain Link | Crown | Large anchor style chain with small metal poles, spaced between two light poles. Entry Last Updated : 3/18/2015 | LEVEELOG |
| 589 | 3.28 | 3.28 | Structure | Sign | Water Side | River Walk display at WS hinge. Entry Last Updated : 3/18/2015 | LEVEELOG |
| 65 | 3.28 | 3.28 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|--------------|------------|--|----------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 590 | 3.29 | 3.29 | Structure | Other | Water Side | Picnic table by concrete WS walkway. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 593 | 3.29 | 3.29 | Structure | Other | Land Side | Bench on the landside hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 592 | 3.29 | 3.29 | Structure | Sign | Water Side | River Walk display at WS hinge. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 66 | 3.29 | 3.29 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 594 | 3.30 | 3.30 | Structure | Other | Land Side | Bench on the landside hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 596 | 3.30 | 3.30 | Structure | Stairs | Water Side | Stairs with metal railings and winding ramp on the waterside slope. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 4 | 3.30 | 3.30 | Structure | Pole | Water Side | Flag pole at WS hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 98 | 3.30 | 3.30 | Structure | Pole | Water Side | Flag pole at WS hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 595 | 3.30 | 3.30 | Structure | Sign | Land Side | "Prohibited" sign on two wood posts by LS hinge. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 597 | 3.30 | 3.30 | Ramp | Ramp | Land Side | Ramp to G St with pavers and metal railing. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 599 | 3.31 | 3.31 | Structure | Sign | Land Side | Granite plaque at LS hinge. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 600 | 3.31 | 3.37 | Structure | Building | Land Side | Ziggurat building on the landside. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 601 | 3.31 | 3.33 | Fence | Chain Link | Crown | Large anchor style chain with small metal poles, spaced between two light poles. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 67 | 3.31 | 3.31 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|---------------|------------|--|----------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 603 | 3.31 | 3.31 | Structure | Control Box | Water Side | Two electric control boxes at WS hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 602 | 3.32 | 3.32 | Structure | Other | Land Side | Bench on the landside hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 604 | 3.32 | 3.32 | Structure | Sign | Water Side | River Walk display at WS hinge. Entry Last Updated : 3/26/2015 | LEVEELOG | | |
| 605 | 3.32 | 3.32 | Structure | Other | Land Side | Bench on the landside hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 606 | 3.32 | 3.32 | Structure | Sign | Crown | Granite plaque about salmon cannery on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 69 | 3.32 | 3.32 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 607 | 3.33 | 3.33 | Structure | Sign | Water Side | River Walk display at WS hinge. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 608 | 3.33 | 3.33 | Structure | Other | Land Side | Bench on the landside hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 70 | 3.34 | 3.34 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 610 | 3.34 | 3.34 | Structure | Control Box | Water Side | Two electric control boxes at WS hinge. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 609 | 3.34 | 3.34 | Structure | Other | Land Side | Bench on the landside hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 611 | 3.35 | 3.35 | Structure | Stairs | Water Side | Concrete stairs with metal railings leading from crown to WS concrete walkway. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 612 | 3.35 | 3.35 | Structure | Manhole Cover | Crown | Monument manhole cover. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 71 | 3.35 | 3.35 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|--------------|------------|--|----------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 613 | 3.36 | 3.36 | Structure | Sign | Water Side | River Walk display at WS hinge. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 614 | 3.36 | 3.36 | Structure | Other | Land Side | Bench on the landside hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 616 | 3.36 | 3.41 | Ramp | Ramp | Water Side | Asphalt pedestrian ramp with bollards from crown to WS concrete walkway. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 72 | 3.36 | 3.36 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 617 | 3.37 | 3.37 | Structure | Sign | Water Side | River Walk display at WS hinge. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 618 | 3.37 | 3.37 | Structure | Other | Land Side | Bench on the landside hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 74 | 3.38 | 3.38 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 619 | 3.38 | 3.38 | Structure | Other | Land Side | Bench on the landside hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 620 | 3.38 | 3.38 | Structure | Sign | Land Side | "Prohibited" sign on two wood posts at LS hinge. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 621 | 3.38 | 3.38 | Ramp | Ramp | Land Side | Paved ramp/road gradually slopes from crown to LS. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 75 | 3.39 | 3.39 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 623 | 3.39 | 3.39 | Structure | Sign | Water Side | River Walk display at WS hinge. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 622 | 3.39 | 3.39 | Structure | Other | Land Side | Bench on the landside hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 76 | 3.40 | 3.40 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|--------------|------------|--|----------------------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 624 | 3.40 | 3.40 | Structure | Other | Land Side | Bench on the landside hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 625 | 3.41 | 3.41 | Structure | Sign | Water Side | River Walk display at WS hinge. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 77 | 3.41 | 3.41 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 626 | 3.41 | 3.43 | Fence | Chain Link | Crown | Large anchor style chain with small metal poles, spaced between two light poles. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 628 | 3.42 | 3.42 | Structure | Other | Land Side | Bench on the landside hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 45 | 3.42 | 3.42 | UCIP | Pipe | Crossing | DS_ID:271 EP_NO: 16702 Crossing Status: Not Found FIELD_STRUCT_DESC: 4.5-inch polyvinyl chloride (PVC) irrigation pipe through the levee, 2 feet below the crown. Public facilities and four stairways on the levee slope. Observation/fishing dock on the waterside (WS). (4-inch irrigation pipe and 1-inch potable water main line authorized under Permit No. 16702, 1997 - City of West Sacramento). Entry Last Updated : 4/17/2021 | UCIPAPR2021 16702 | | |
| 627 | 3.42 | 3.42 | Structure | Sign | Water Side | River Walk display at WS hinge. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 78 | 3.42 | 3.42 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 629 | 3.42 | 3.42 | Structure | Other | Land Side | Bench on the landside hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 630 | 3.43 | 3.43 | Structure | Stairs | Water Side | Two sets of concrete stairs separated by flower planter box. Stairs have metal railings and go from crown to WS concrete walkway. Entry Last Updated : 3/26/2015 | LEVEELOG | | |
| 631 | 3.43 | 3.45 | Fence | Chain Link | Crown | Large anchor style chain with small metal poles, spaced between two light poles. Entry Last Updated : 3/18/2015 | LEVEELOG | | |

**Flood Control Project Maintenance
Levee Inspections
Levee Log Report By Levee Mile - Updated 8/23/2021**

Sacramento Maintenance Yard Maintenance Area 0004

| Waterway | | | | | | | Bank | Unit Miles | Inspector |
|------------------------------|------------|------|-----------|--------------|------------|---|--------------|------------|--------------|
| Unit No. 01 Sacramento River | | | | | | | Right | 3.47 | David Julian |
| Entry No | Levee Mile | | Category | Item | Location | Comment | Source | | |
| | Start | End | | | | | Permits | | |
| 632 | 3.44 | 3.44 | Structure | Other | Land Side | Bench on the landside hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 79 | 3.44 | 3.44 | Structure | Pole - Light | Crown | Entry Last Updated : 8/25/2020 | LEVEELOG | | |
| 633 | 3.44 | 3.44 | Structure | Sign | Water Side | River Walk display at WS hinge. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 634 | 3.45 | 3.45 | Structure | Other | Land Side | Bench on the landside hinge. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 635 | 3.45 | 3.45 | Structure | Sign | Crown | "Prohibited" sign on two wood posts on crown. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 637 | 3.45 | 3.45 | Structure | Other | Crown | Bike locks on crown. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 80 | 3.45 | 3.45 | Structure | Pole - Light | Crown | Light pole on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 638 | 3.45 | 3.45 | Structure | Sign | Crown | River Walk sign supported on two large black poles on the crown Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 636 | 3.45 | 3.45 | Structure | Other | Crown | Bench on crown. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 639 | 3.46 | 3.46 | Structure | Other | Crown | "A Life's Ride" sculpture on the crown. Entry Last Updated : 1/27/2021 | LEVEELOG | | |
| 640 | 3.46 | 3.46 | Structure | Sign | Crown | River Walk display on crown by Tower Bridge. Entry Last Updated : 3/18/2015 | LEVEELOG | | |
| 244 | 3.47 | 3.47 | Mark | Boundary | Crown | End of unit at the Tower Bridge, northern boundary of Reclamation District No. 900. Entry Last Updated : 3/11/2015 | H_LL_GENERAL | | |